



ИНСТРУКЦИЯ ПО СБОРКЕ

ТЕМПЕРЕ стеллаж 4





-  (D) Montageanleitung
(FR) Notice de montage
(NL) Handleiding voor de montage
(CZ) Montážní návod
(HU) Szerelési útmutató
(TR) Montaj talimatları

- (GB) Assembly instructions
(IT) Istruzioni di montaggio
(PL) Instrukcja montażu
(SK) Návod na montáž
(RO) Instrucțiuni de montaj



50 min



Name • Nom • Nome • Naam • Nazwa • Jaméno
• Názov • Név • Denumire • Isim

Nr. • No. • N° • Č • Sz


Typ • Type • Tip • Tipus • Tipo

No	Size/MaB	Qty	✓
1	1762x100x20	4	
2	1968x250x20	2	
3	1426x250x20	2	

C8 x14	C9 x14	J2 x8 4x16	
G1 x4	V1 x4	Z2 x28	W2 x4



1
x2

J2 x8



4x16

W2 x4




W2


TOP







J2

1 x2



x4







Z2 **x28**

An isometric drawing of a bolt, showing its hexagonal head and threaded shaft. The bolt is oriented diagonally, with the head at the top left and the shaft extending towards the bottom right. The drawing is a simple line representation without shading.

C9 **x14**



Z2


①

1"


1

C9


C9



③ x2



② x2



C8

